

| Site Name | Feature Location | 6 D's | Reasons | Existing species | Planting notes | Replant species |
|------------------|---|----------|---|------------------|---|-----------------------------------|
| LADYSMITH AVENUE | o/s 26 | Damaging | Kerbs tipped/uplifted and rooting into c/w - unable to to repair with tree insitu | Tilia x europea | Plant in new 800mm pit o/s 26 (same as felled tree) | Tilia cordata X mongolica 'Har |
| LADYSMITH AVENUE | o/s 14 | Damaging | Extensive rooting into c/w - kerbstones absent | Tilia x europea | Plant in new 800mm pit o/s 14 (same as felled tree) | Tilia cordata X mongolica 'Har |
| LADYSMITH AVENUE | o/s 15 | Damaging | Kerbs absent, rooting into c/w - no way to repair with tree insitu | Tilia x europea | Plant in new 800mm pit o/s 15 (same as felled tree) | Tilia cordata X mongolica 'Har |
| LADYSMITH AVENUE | OPPOSITE 11 | Damaging | Rooting through/between kerbs into c/w - no way to repair with tree insitu | Tilia x europea | Plant in new 800mm pit OPPOSITE 11 (same as felled tree) | Tilia cordata X mongolica 'Har |
| LADYSMITH AVENUE | OPPOSITE 7 | Damaging | Kerbs missing, cannot repair or replace without causing unacceptable damage to tree | Tilia x europea | Plant in new 800mm pit OPPOSITE 7 (same as felled tree) | Tilia cordata X mongolica 'Har |
| LADYSMITH AVENUE | opp 5 | Damaging | Kerbs absent, rooting into c/w, cannot repair without causing unacceptable damage to roots | Tilia x europea | Plant in new 800mm pit OPPOSITE 5 (same as felled tree) | Tilia cordata X mongolica 'Har |
| LADYSMITH AVENUE | adj rear of 19 Barkers rd, (level with wooden gate for no 19) | Damaging | Kerbs absent, rooting into c/w, cannot repair without causing unacceptable damage to roots | Tilia x europea | Plant in new 800mm pit adjacent side of 19 Barkers Rd (same as felled tree, just above wooden gate) | Tilia cordata X mongolica 'Har |
| LADYSMITH AVENUE | S/O 19 Barkers Rd, 1st tree on street | Damaging | Kerbs absent, rooting into c/w, cannot repair without causing unacceptable damage to roots | Tilia x europea | Plant in new 800mm pit adjacent side of 19 Barkers Rd (same as felled tree, 2nd 1 of 2 here) | Tilia cordata X mongolica 'Har |

| LADYSMITH AVENUE | adj side of 17 Barkers rd, 1st tree on street | Damaging | Kerbs absent, rooting into c/w, cannot repair without causing unacceptable damage to roots | Tilia x europea | Plant in new 800mm pit adjacent side of 17 Barkers Rd (same as felled tree, 2nd 1 of 2 here) | Tilia cordata X mongolica 'Har |
|------------------|---|----------|--|-----------------|--|-----------------------------------|
| LADYSMITH AVENUE | adj side of 17 Barkers rd (just below substation) | Damaging | Kerbs absent, rooting into c/w, cannot repair without causing unacceptable damage to roots | Tilia x europea | Plant in new 800mm pit adjacent side of 17 Barkers Rd (same as felled tree, just below substation) | Tilia cordata X mongolica 'Har |